

Archived: Tuesday, May 03, 2016 8:33:21 AM

From: Jason P Ericson (Services - 6)

Sent: Monday, May 02, 2016 5:15:00 PM

To: Glassman, Joseph (DEQ)

Cc: Chapman, Randy (DEQ); John Black (VirginiaPower - 1); Jason E Williams (Services - 6); Amanda B Tornabene (Services - 6); John D Dicarlo (VirginiaPower - 1); Brett W Paulin (Services - 6); Paula A Hamel (Services - 6)

Subject: Crystal Substation and Roaches Run Weekly Update: May 2, 2016

Importance: Normal

Mr. Glassman,

As requested in your February 23, 2016 letter, below is the weekly update for activities at the Crystal Substation and at Roaches Run/Gravelly Point.

If you have any questions please contact John Black or me.

Thank you,
Jason

Jason P. Ericson, PG
Dominion Resources Services, Inc.
Environmental Policy
5000 Dominion Blvd
Glen Allen, VA 23060
Phone: (804) 273-3012
Mobile: (804) 317-9464
Fax: (804) 273-2964

**Crystal Substation Daily
Inspection Notes and Summary: May 2, 2016**

Summary Monday April 25 – Friday April 29: No sheen or oil was observed at any of our inspection areas this week. No accumulations of water or oil in vaults were observed inside or outside the Station.

Below you will find our daily observations for inspections:

Monday April 25, 9:30 am (high tide) – The storm water drop inlet outside the Station showed no signs of oil or sheen. Roaches Run outfall showed no signs emulsified oil. Gravelly Point boat launch area showed no signs of oil or sheen. Roaches Run parking area showed no signs of oil or sheen. All vaults were empty.

Tuesday April 26, 7:30 am (low tide) – The storm water drop inlet outside the Station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil. Gravelly Point boat launch area showed no signs of oil or sheen. Roaches Run parking area showed no signs of oil or sheen. All vaults were empty.

Wednesday April 27, 10:30 am (high tide) – The storm water drop inlet outside the Station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil. Gravelly Point boat launch showed no amount of sheen at boat ramp or dock area. Roaches Run parking area showed no signs of oil or sheen. All vaults were empty.

Thursday April 28, 12:00 pm (high tide) – The storm water drop inlet outside the Station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil, and absorbent boom was changed as a precaution. Gravelly Point boat launch area showed no signs of oil or sheen. Roaches Run parking area showed no signs of sheen. All vaults were empty.

Friday April 29, 7:09 am (low tide) – The storm water drop inlet outside the station showed no signs of oil or sheen. Roaches Run outfall showed no signs of emulsified oil. Gravelly Point boat launch area showed no signs of oil or sheen. Roaches Run parking area showed no signs of oil or sheen. Hepaco, Inc. pumped standing rain water (approximately 1200 gallons) from all four lined containments around the transformers.

Jason P. Ericson, PG
Dominion Resources Services, Inc.
Environmental Policy
5000 Dominion Blvd
Glen Allen, VA 23060
Phone: (804) 273-3012
Mobile: (804) 317-9464
Fax: (804) 273-2964

CONFIDENTIALITY NOTICE: This electronic message contains information which may be legally confidential and or privileged and does not in any case represent a firm ENERGY COMMODITY bid or offer relating thereto which binds the sender without an additional express written confirmation to that effect. The information is intended solely for the individual or entity named above and access by anyone else is unauthorized. If you are not the intended recipient, any disclosure, copying, distribution, or use of the contents of this information is prohibited and may be unlawful. If you have received this electronic transmission in error, please reply immediately to the sender that you have received the message in error, and delete it. Thank you.